
## MODIFICATION TO 98 SENTRA SR20 ECU HARNESS TO RUN A '95-97 SENTRA SR20 ECU

The following wire must be relocated as shown below to allow a 1995-97 ECU to run correctly in a 1998 SR20 SENTRA. The diagram is shown from the harness side (the side the wires are on).



The <u>rear</u> O2 sensor must be changed to a EARLY 3 WIRE type sensor or the MIL light will come on. Transfer the plastic electrical plug from the original 4 WIRE sensor to the new EARLY 3 WIRE sensor using the diagram numbers.

- EARLY 3 WIRE sensor wire # 1 inserts in 4 WIRE plug hole #1
- EARLY 3 WIRE sensor wire # 2 inserts in 4 WIRE plug hole #2
- EARLY 3 WIRE sensor wire # 3 inserts in 4 WIRE plug hole #4
- 3 WIRE sensor does not need the additional ground wire so the 4 WIRE O2 connecter hole #3 is no longer used.
- An 18 m.m. to 12 m.m. bushing or adapter must be made to physically install the earlier 12 m.m. sensor



## VIEWED FROM PIN SIDE OF 02 SENSOR

